

2-1-90

Dear Sirs:

The enclosed rifle (model 700 BDL 270 cal., serial # 6479 664) has fired several times by itself. Twice when I was loading a shell, when the bolt was completely seated the rifle fired. Once after the shell was loaded and the bolt ~~seated~~ seated, I flipped the safety to fire and the rifle fired.

I was told by your ~~sub~~ authorized dealer in San Antonio (Nagel Gun Shop, 6201 San Pedro Av. 78216) that this model gun had some problems and that it had to be sent back to you for warranty work. They would not work on it. I bought the gun in 1970 at Sears & Roebuck. I was not notified at any time by anyone that there was anything wrong with this rifle. It has never been worked on by any gunsmith. I would appreciate your cooperation in getting my rifle repaired.

Thank you,

(Tel # 512-333-8212)

Tommy Dziuk
131 Hatcher
SAN ANTONIO, TX 78223