

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

December 19, 1988

Leslie Edelman, Inc.
465 Route 46 West
Wayne, NJ 07470

Re: Your Repair No. 10805

Gentlemen:

Examination has been completed on the Model 700 BDL 270 Win. caliber rifle, serial number B6733345, that you returned to us a short time ago because "...the gun fires as soon as safety is turned to fire, gun fires automatically".

The returned firearm, which was produced in July of 1985, was found to bear our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to shipment from our factory.

The general condition of the gun appeared to be very good, however, it was noted that the stock contained numerous scratches and mars. In going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not duplicate the condition that was reported. Factory seals were intact on the trigger adjustment screws, indicating that no adjustment had been made to the trigger outside our factory. Trigger pull was measured to be 5 1/2 pounds, and sear lift with the safety in the "on-safe" position was well within specifications at .014". The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed.