

PROJECT#241095

#3

BARBER - 5.22.06r0001570

NAME			DATE		TEST ACTIVITY		COMMENTS		ROUNDS AT START-0	
									RDS. FIRED	TOTAL RDS.
JA/SW	12/8/00	Preliminary Measurements (Done)								
Jesse	12-10-00	Jack Function Test	100	rels					100	100
JA/SW	12/13/00	Clean & Inspect								
PKR	12/13/00	Straighten	Front	of Rear	of Mag Box					
Jesse	12/14/00	Jack Function Test	400	rels					400	500
Jessie	12/15/00	Clean & Inspect								

Coverpg:

ET07401

~~Confidential - Subject~~ - 592506001576 Order

Subscriber - 5.2.2.Protection Order

Williams v. Remington

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
315 WEST RING ROAD
ELIZABETHTOWN, KY 42701

Clean & Inspect Checklist, Series C T&P

Model: 710Project: 241095Rifle: C-7TLW #: TLW0300Date: 12 / 15 / 00Inspector: PesceRound Level: 500☒ Measure Headspace Min +.003☒ Sear Engagement: .0281☒ Trigger Pull: 1st. 4.5 2nd. 4.0 3rd. 3.75 Ave. 4.08

Check the following areas for signs of unusual wear or breakage:

☒ Receiver insert☒ Rear surface of Bolt Lugs☒ Check for "galling" on rear of Bolt Lugs☒ Bolt Plug☒ Bolt Plug Insert "ears" on firing pin assembly☒ Check for loose or missing pins - make note and re-stake if necessary☒ Check plastic inserts for cracks or other damage.☒ Firing Pin Head for Looseness.☒ Check Firing Pin Tip for Looseness.☒ Check Take Down Screws for Movement. Show new position relative to original mark. de Rear Middle Front

Position after re-torque:

 de Rear Middle Front☒ Check Diaz Bracket Screw for looseness.☒ Check Bolt Stop: Slight Movement of Material

Take digital photographs, if appropriate, to record unusual wear, damage or other note-worthy observations. List the digital file name for reference along with any comments below: _____

TLW0300

TESTPLAN_Rev1_C_Series.doc

Remington Confidential

Revision # 1

ET07402