

CAL.- 30.06

#3

PROJECT#241095

NAME			DATE		TEST ACTIVITY		COMMENTS		ROUNDS AT START - ϕ	
									RDS. FIRED	TOTAL RDS.
JA/SW			12/8/00		Preliminary Measurements (Done)					
Jesse			12-10-00		Jualc Function Test 100 rd Level				100	100
JA/SW			12/12/00		Clean + Inspect					
PKR			12/13/00		Straighten Front & Rear of Mag Box					
Jesse			12/14/00		Jualc Function Test 400 rd				400	500
Jesse			12/15/00		Clean + Inspect					

Coverpg

BARBER - 5.22.06r0001574

1

ET07405

~~Confidential - Subject~~ - 502-569-001574 Order

Subj: **PROPOSITIVE** Order
 S/N: **5.2.2.061001574**

Williams v. Remington

Remington Arms Company Inc.
 RESEARCH & DEVELOPMENT TECHNICAL CENTER
 315 WEST RING ROAD
 ELIZABETHTOWN, KY 42701

Clean & Inspect Checklist, Series C T&P

Model: 710Project: 241095Rifle: C-9TLW #: TLW0300Date: 12 / 15 / 00Inspector: DeaneRound Level: 500☒ Measure Headspace Min + .003☒ Sear Engagement: .0244☒ Trigger Pull: 1st. 3.75 2nd. 3.5 3rd. 3.75Ave. 3.66

Check the following areas for signs of unusual wear or breakage:

☒ Receiver insert☒ Rear surface of Bolt Lugs☒ Check for "galling" on rear of Bolt Lugs☒ Bolt Plug☒ Bolt Plug Insert "ears" on firing pin assembly☒ Check for loose or missing pins - make note and re-stake if necessary☒ Check plastic inserts for cracks or other damage.☒ Firing Pin Head for Looseness. Loose☒ Check Firing Pin Tip for Looseness.☒ Check Take Down Screws for Movement. Show new position relative to original mark.Rear oleMiddle oleFront ole

Position after re-torque:

Rear oleMiddle oleFront ole☒ Check Diaz Bracket Screw for looseness.☒ Check Bolt Stop slight vertical movement

Take digital photographs, if appropriate, to record unusual wear, damage or other note-worthy observations. List the digital file name for reference along with any comments below.

TLW0300

TESTPLAN_Rev1_C_Series.doc

Remington Confidential

Revision # 1

ET07406