

CAL.- 30.06

#3

PROJECT#241095:

[illegible]

Coverpg.

BARBER - 3.22.06 F0001378

6

Remington Arms Company Inc.
 RESEARCH & DEVELOPMENT TECHNICAL CENTER
 - 315 WEST RING ROAD
 ELIZABETHTOWN, KY 42701

Clean & Inspect Checklist, Series C T&P

Model: 710Project: 241095Rifle: C-11TLW #: TLW0300Date: 12 / 15 / 00Inspector: JesseRound Level: 500☒ Measure Headspace Min +.004☐ Sear Engagement: .0253☒ Trigger Pull: 1st. 5.0 2nd. 5.0 3rd. 4.75Ave. 4.92

Check the following areas for signs of unusual wear or breakage:

☒ Receiver insert☒ Rear surface of Bolt Lugs☒ Check for "galling" on rear of Bolt Lugs☒ Bolt Plug☒ Bolt Plug Insert "ears" on firing pin assembly☒ Check for loose or missing pins - make note and re-stake if necessary☒ Check plastic inserts for cracks or other damage.☒ Firing Pin Head for Looseness. Loose☒ Check Firing Pin Tip for Looseness.☒ Check Take Down Screws for Movement. Show new position relative to original mark. ol Rear ol Middle Front

Position after re-torque:

 ol Rear Middle Front☒ Check Diaz Bracket Screw for looseness. _____☒ Check Bolt Stop slight material movement

Take digital photographs, if appropriate, to record unusual wear, damage or other note-worthy observations. List the digital file name for reference along with any comments below:

TLW0300

TESTPLAN_Rev1_C_Series.doc

Remington Confidential

Revision # 1

ET07410