

CAL.- 30.06

#3

PROJECT#241095

CAL - 50.00			ROUNDS AT START - 0		
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
JA/SW	12/8/00	Preliminary Measurements (Done)			
Jesse	12/10/00	Function check of IIS system (Pass)			
Jesse	12/11/00	Tack Function Test	100 rd Level	100	100
JA/SW	12/12/00	Clean & Inspect			
MDM	12/14/00		MODIFIED SPRING FOR BOX REPAIRS		
"	"		MODIFIED BOX BOTTOM		
Jesse	12-19-00	Tack Function Test	400 rd	400	500
Jesse	12/15/01	Clean & Inspect			

Coverpg :

BARBER - 5.22.06r0001580

—

ET07411

Confidential - ~~SHARPER~~ 5922060001580
Williams v. Remington

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
 315 WEST RING ROAD
 ELIZABETHTOWN, KY 42701

Clean & Inspect Checklist, Series C T&P

Model: 710Project: 241095Rifle: C-12TLW #: TLW0300Date: 12-15-100Inspector: JesseRound Level: 500☒ Measure Headspace: Min + .002☒ Sear Engagement: .0250☒ Trigger Pull: 1st 4.0 2nd 4.5 3rd 4.0Ave. 4.17
~~4.17~~

Check the following areas for signs of unusual wear or breakage:

- ☒ Receiver insert
- ☒ Rear surface of Bolt Lugs
- ☒ Check for "galling" on rear of Bolt Lugs
- ☒ Bolt Plug
- ☒ Bolt Plug Insert "ears" on firing pin assembly
- ☒ Check for loose or missing pins - make note and re-stake if necessary
- ☒ Check plastic inserts for cracks or other damage.
- ☒ Firing Pin Head for Looseness.
- ☒ Check Firing Pin Tip for Looseness.
- ☒ Check Take Down Screws for Movement. Show new position relative to original mark.

 Rear
  Middle
  Front

Position after re-torque:

 Rear
  Middle
  Front

☒ Check Diaz Bracket Screw for looseness. _____☒ Check Bolt Stop: slight rotational movement

Take digital photographs, if appropriate, to record unusual wear, damage or other note-worthy observations. List the digital file name for reference along with any comments below. _____

TLW0300

TESTPLAN_Rev1_C_Series.doc

Remington Confidential

Revision # 1

ET07412