

## EMERSON AND SON, INC.

28 STATE STREET

GROVETON, N.H. 03582

[603] 636-1220

②

TO The safety to the fire position. The gun could also discharge simply by slamming the bolt closed on a live round. It appears to me that the trigger fits so tightly in the housing that it interferes with the return of the trigger.

I have called the recall 800 number and they informed me that this gun's trigger mechanism wasn't a recalled one - but it sure should have been.

My customer is pretty upset with the response I got when I called and I was told that it would take 3-5 weeks to get his gun fixed, but had it been a recalled gun it would only be 5-6

SIGNED

FORM 01-87 • DISTRIBUTED BY BULL CORPORATION • 100 S. SCHULTZ ROAD • LOMBARD, ILLINOIS 60149