

M/600 Customer
ComplaintP.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 600GENERAL CONDITION: GOOD R # : 10844OUTSIDE WORK: TRIGGER HOUSING ADJUSTMENTS DATE: 5-17-71UNSEALED & CHANGED. FROM: JOSEPH D. FUDYFIRED AMMO TYPE: _____ KINSTON, N.C.& CONDITION: _____ GUN # : 80913PROOF: R.E.P. INSP.: 76 TEST: 13 CODE: CP-4/67HEADING: O.K. GA./CAL.: 243BREECH OPENING: - CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN, DAMAGED COMPONENTS. EVIDENCE OF DRIED
LUBRICANT INSIDE TRIGGER HOUSING.COMPLAINT: "IF COCKED WITH SAFETY ON AND TRIGGER IS PULLED
WHEN THE SAFETY IS RELEASED IT WILL FIRE, SOMETIMES
IT WILL NOT COCK ON CLOSING."INCIDENT: FOLLOWS DOWNCOMMENTS: IT APPEARS THAT THE DRIED LUBRICANT CAUSED
THE TRIGGER AND SEAR TO REMAIN IN FIRED POSITION
AFTER FIRING.