

BARBER - Kinzer PPS GAL RE0001668

INITIAL LCS	CUSTOMER ORDER NO. 3818											
DATE RECEIVED 10/02/90	DATE OPENED 10/10/90	DATE CODE KH 5-87	SERIAL NUMBER B6862048	MODEL AND GRADE 700 270 BDL		ORDER R 90-2						
ACCESSORIES W/STUDS		L/SIGHTS										

FROM:

EWELL CROSS GUN SHOP
P.O. BOX 3025
8240 I-30 WEST
FT WORTH TX 76108

SHIP TO:

EWELL CROSS GUN SHOP
P.O. BOX 3025
8240 I-30 WEST
FT WORTH TX 76108

TX 76108

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"This gun fired when the safety was pushed off"

MAIN FAULT

Entire trigger assembly is contaminated with a sticky residue (WD-40). The rear-safety cam is stuck solidly to the side plate of the trigger assembly and is inoperative. Rifle has not been properly maintained.

PARTS

Send quotation to replace trigger assembly at normal price, as system of gun will.

REPAIRMAN [Signature]	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

26925 RE-