

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

November 11, 1986

Mr. Charles E. Fenner, III
541 Cushing Ct.
Brookings, Oregon 97415

Dear Mr. Fenner:

This is in reply to your letter of October 27, 1986 regarding the accidental firing of your Remington Mohawk 600 rifle, serial number A6390843.

As we are very much interested in determining the cause of this alleged firing upon safety release situation, please package your Mohawk 600 rifle and send it via United Parcel Service, Transportation COD, to:

Remington Arms CO., Inc.
Rush to: R.H. Potter
Ilion, NY 13357

Enclosed for your use are three (3) blaze orange stickers which should be affixed to both butt ends and to the top of the outside of the package. This will give you more timely service.

When we receive your rifle, our experts will try to duplicate the incident or analyze the fire assembly in such a way we can verify how the incident could have occurred. If Remington is found at fault in any way, we will assume complete responsibility for your truck repair bill.

However, if the incident cannot be duplicated or if we cannot find any fault with the rifle, we will install at no charge a new fire assembly in your Mohawk 600 rifle so that you can have complete confidence in your firearm in the future.

Thank you for calling this matter to our attention, Mr. Fenner, and for giving us this opportunity to be of service to you.

Sincerely,

R.H. Potter, Supervisor
Product Service