

RECEIVING AND ESTIMATING REPORT

CUST NO: 048525 C.O.D.
CUSTOMER ORDER NO.

COMMENTS

STEKO

ED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
9/91	09/04/91	XC 12-82	B6432968	700 22-250 BDL/VAR	R 91-17382
SERIES			W/STUDS		

DM:

FISHER, WILLIAM H
RTE 1 STAR RT 679
BOX 417
FINCASTLE
USA

VA 24090

SHIP TO:

FISHER, WILLIAM H
RTE 1 STAR RT 679
BOX 417
FINCASTLE
USA

VA 24090

DUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

9/20/91

UPS

R CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CONDITION:

☐

NEW

☐

SLIGHTLY WORN

☐

VERY WORN

☐

MISUSED

☐

MARRED

OWNER'S REQUEST

"This gun fired when loading. It won't stay loaded part of the time. I think there's a problem with the trigger assembly."

FAULT

Trigger assembly has been improperly adjusted outside of factory - calant missing from adjustment screws. Trigger pull mechanism only 1 round - trigger retention spring force is non-existent. Firing pin will follow down on bolt closing because of above condition 2) excessive web-travel. Seal left .0125"

Send quote for new trigger assembly at 1/2 normal price, as good-will gesture.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE