

William H. Fisher

Route 1, Box 417 State Rt. 679

Fincastle, VA 24090

Remington Repair Service

Remington 700 Heavy Barrel 22:250

SN - B6432968

This gun fired when loading, It won't stay cocked part of the time. I think there is a problem with the trigger Assy.

There is also a problem with the Latch where you take the bolt out of the gun it don't come back down when you put the bolt back in the gun.