

CAL.- 30.06

#3

PROJECT#241095:

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START- Φ	
				RDS. FIRED	TOTAL RDS.
JA/SW	12/9/00	Preliminary Measurements (Done)			
Jesse	12-11-00	Fail Function Test 100 rd Level		100	100
JA/SW	12-11-00	Cleaned / Inspected			
SW	12/14/00	Heat Humidity Test	TLW0300AT Put Gun C23 and 100 Round of 2mm in environmental test chamber 4:00 Shoot 100 Round 2mm. Take gun C23 and 20 Round 2mm from environmental test chamber. (Cycle safety every five rounds.) Repeat every 2 hours until all 100 rounds have been shot. Check temperature and humidity before shooting each 20 round.		
SW	12/15/00	Clean + Inspected	Everything OK	100	200

Coverpg.

BARBER - 5.22.06r0001595

10