

Five Points Sport Shop, Inc.

P. O. Box 132

ROUTE 512 — SANGOR, PENNSYLVANIA 18013

215-582-4143

RECEIVED

MAR - 21 1981

J. A. STEKL

Remington Arms Company,
Ilion, New York 13357

Dear Sirs,

This reply is in reference to
Model 700 Rifle 6573276, Repair Order
R 8200-700. In examining the rifle at
my place of business I did find the firing
mechanism defective. However no inhibitors
have been occurred by my business.

Therefore I would like the
rifle's firing mechanism repaired or replaced
and returned as soon as possible

Sincerely,

John J. F. Smith