

Customer Complaint.

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 S&W
 GENERAL CONDITION: GOOD R #: 24953
 OUTSIDE WORK: NO DATE: 10-28-70
 FROM: FLORENCE, MINN.
 FIRED AMMO TYPE: _____
 & CONDITION: _____ GUN #: 6837851
 PROOF: R.E.P. INSP.: _____ TEST: _____ CODE: CT = 4/70
 HEADING: O.K. GA./CAL.: 25-06
 BREECH OPENING: _____ CHECKED BY: C. P. ROBERTS
 RECOIL SHOULDERS: _____ APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: "BULLET STICKS IN CHAMBER ALSO BOLT IS IMMOVABLE FOR SOME REASON."

INCIDENT: _____

COMMENTS: THE CUSTOMER PULLED THE BULLET OUT OF THE CASE LEAVING IT IN THE THROAT. THIS APPARENTLY IS AN AMMUNITION PROBLEM (PER M. WALKER).
THE BOLT CATCHING IS CAUSED BY PUSHING THE SAFETY ON BEFORE LOCKING THE BOLT THUS CATCHING THE SAFETY ARM IN THE COCKING CAM.