

Carl Cuyler

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: NEW R #: 003187
 OUTSIDE WORK: NO DATE: 1-30-73
 FROM: J. FOSTER

FIRE AMMO TYPE: - LYNCHBURG, VA.

& CONDITION: _____ GUN #: 6326074

PROOF: R.E.P.-A INSP.: 9 TEST: 55 CODE: CT = 4/70

HEADING: O.K. GA./CAL.: 25-06

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR-TRIGGER CLEARANCE = 1.084 (MODEL 1.080) (DRAWING 1.083) TRIGGER-
CONNECTOR CLEARANCE = 1.072 (1.076) (1.079) CENTER LINE OF PIN HOLE
TO TOP OF TRIGGER = .974 (.973) (.971) CENTER OF PIVOT HOLE
IN SAFETY TO TOP OF CAM = .291 (.292) (.296)

COMPLAINT: "FIRED WITH SAFETY ON"

INCIDENT: FOLLOW DOWN

COMMENTS: THE RIFLE WILL NOT FIRE WITH THE SAFETY ON.
THE CONDITIONS LISTED ABOVE: .005 TOO MUCH CLEAR-
ANCE BETWEEN CONNECTOR & TRIGGER, TOP OF TRIGGER
.001 OVER MIN. AND SAFETY .001 UNDER MIN., ALL
CONTRIBUTE TO AN INTERFERENCE BETWEEN THE
CONNECTOR AND SEAR WHICH WOULD PREVENT
RETRACTION INTO COCKED POSITION TO CAUSE FOLLOW
DOWN.