BARBER - Kinzer PPS GAL RE000181

SEP 4 1984

CONSUMER SERVICE

RECEIVED

BEP . . 1984

J. A. STEKL

Dixon H. Fotheringham 667 N. 1050 W. St. George, Utah 84770

Aug. 21, 1934

Remington Arms Co, Inc. Bridgeport, CF 06601

Gentlemen:

I am a Remington Gun fan and own four of them. Two Model 970 "Special Field" shot guns, and two Model 700 EDL rigles. One in .30/06 calbre and one in .243 calibre.

I am having trouble with both of the Model 700 rifles in that they quite often discharge when letting off the safety. This is very unsafe when hunting with a group.

Is there something that can be done about this problem? If so, where in this area?

Verw truly & concerned yours

•