

N/700 Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: NEW R #: 016257
OUTSIDE WORK: NO DATE: 8-16-72
FROM: HENRY L. FRAME
FIRED AMMO TYPE: - W. BARRINGTON, R.I.
& CONDITION: _____ GUN #: 297377
PROOF: R.E.P. INSP.: 14 TEST: 49 CODE: WR = 8/68
HEADING: _____ GK./CAL.: 270 WIN.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER PULL 3 1/2 LBS., SEAR-TRIGGER CONNECTOR
ENGAGEMENT .005 (MIN. IS .020) STICKY LUBRICANT
INSIDE HOUSING, CORNER OF TRIGGER CONNECTOR
WORN ROUND.

COMPLAINT: "IT DISCHARGES PREMATURELY"

INCIDENT: FOLLOW DOWN

COMMENTS: WITH INSUFFICIENT ENGAGEMENT BETWEEN
SEAR & CONNECTOR THE CONNECTOR BROKE DOWN
ON THE CORNER ALLOWING THE FOLLOW DOWN
MALFUNCTION.