

Remington Arms

I telephoned your customer service dept. Monday 5-21-84 and they advised me to send the following rifle @ 700 BDL 7mm Mag. for repairs. The rifle accidentally fired while starting to eject a cartridge out of the chamber.

Why the shell fired I have no idea, the only modification done to the rifle was having it glass bedded and the sights taken off all done by a reputable gunsmith, Also the face and extractor ~~area~~ of the bolt show excessive wear for a rifle that has only been shot very little ~~(304 hours)~~. The rifle was bought in 1980 but has been used very little.

Of the many rifle and shotgun I own, most of them are Remingtons-- which I have enjoyed for years and I am confident that this rifle will be checked and repaired if needed.

Thomas C. Franzen I thank you.  
510 3rd Ave.  
WORTHINGTON, Ky. 41085

(606) 836-2493

