

BARBER - Kinzer PPS GAL RE0001846

ATTN JIM STEKL W/J.L. STARK BBL, STOCK NOT OUR
MFG. W/ 1 STUD

INITIAL FJB	CUSTOMER ORDER NO.		DATE RECEIVED 10/19/90		DATE OPENED 10/24/90	DATE CODE	SERIAL NUMBER 6253567	MODEL AND GRADE 700 300 WIN MAG	ORDER R 90-278
ACCESSORIES SCOPE BASE									

FROM:

LES FREER
8928 SPRING BRANCH DR.
BLDG B-1
HOUSTON TX 77080

SHIP TO:

LES FREER
8928 SPRING BRANCH DR.
BLDG B-1
HOUSTON TX 77080

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☒ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: Rifle fired when bolt was closed

MAIN FAULT 1) trigger assembly improperly adjusted outside of factory. 2) engagement surfaces on connector & rear safety cam broken — probably from blown primer. Firing pin so eroded & bolt face is gas cut; this condition resulted from too little rear engagement coupled with primer leakage. Safety lever has been broken off & re-welded. As received, rifle would not cock because of broken rear-connector surfaces. Top rear surface of firing pin had have been filed outside of factory.

Strictly as a gesture of good-will, replace trigger assembly and firing pin assembly at no charge.

Adjusted trigger pull to 3 1/2 pounds per customer request. (Phone call 11/7/90)

11/7/90

Product Service is keeping trigger and firing pin.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7

BARBER - Kinzer PPS GAL RE0001846

PPS 01841