

*Carl. Connel*

P.I. NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700BOL  
GENERAL CONDITION: NEW R #: 024573  
OUTSIDE WORK: SCOPE & RECOIL PAD FITTED. DATE: 11-27-72  
FROM: FRONTIERSMAN  
SPORTS INC.  
MINNEAPOLIS, MINN.  
FIRED AMMO TYPE: -  
& CONDITION: \_\_\_\_\_ GUN #: 6365254  
ASSEMBLER 12  
PROOF: R.E.P. INSP.: 74 TEST: 49 CODE: DT=9/70  
HEADING: O.K. G.K./CAL.: 3006  
BREECH OPENING: - CHECKED BY: C. PROSSER  
RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_  
CHAMBER: O.K. APPROVED: \_\_\_\_\_  
TEST: NO APPROVED: \_\_\_\_\_  
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

SEAR-TRIGGER CONNECTOR ENGAGEMENT .005 (MIN.=.020)

TRIGGER CONNECTOR CLEARANCE ON TRIGGER = 1.075,

M/D =  $\frac{1.076}{1.079}$ ; TRIGGER CLEARANCE ON CONNECTOR = 1.086,

M/D =  $\frac{1.080}{1.083}$ ; FIRING PIN CAN CATCH ON REAR CORNER  
OF HOUSING. LAPPING ON CONNECTOR CROOKED.

COMPLAINT: RIFLE DISCHARGED WHEN LOADING CARTRIDGE.

INCIDENT: FOLLOW DOWN

COMMENTS: THERE IS EVIDENCE OF TRIGGER BIND. THIS COMBINED  
WITH UNDER MIN. ENGAGEMENT AND EXCESSIVE TRIGGER-  
CONNECTOR CLEARANCE, CAUSES FOLLOW DOWN.