

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-0997

INITIAL CUSTOMER ORDER NO.

JJM

BOTTOM HALF OF MOUNTS ONLY

STEKL

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/07/92

04/15/92

AG 3-86

B677B078

700 270

MTN

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SHIP TO:

FURLONG, JIM
RD 2 SILVER CREEK RD
JOHNSONBURG

PA 15845

FURLONG, JIM
RD 2 SILVER CREEK RD
JOHNSONBURG

15845

CUST NO: 060923 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

4/28/92

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D3

METAL

C2

D3

MAIN FAULT

Complaint was duplicated, also, at times the firing pin followed down as the action was closed. Examination of the trigger revealed that the trigger assembly had been improperly adjusted. Trigger pull was only 3 1/2 pounds, and the adjustment reported been locked in for that there was no adjustment spring for at all.

Searlift, 0124

PARTS

COMMENTS

Offer to re-adjust present trigger assembly, or, to install new trigger assembly at a normal cost, as a gift of goodwill, if that will provide me confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATT

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV