

Customer Complaint

F.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: NEW R #: 24701
 OUTSIDE WORK: NO DATE: 12-9-71
 FROM: G.H. Sports Co.
 FIRED AMMO TYPE: — HANDLED, CAL.
 & CONDITION: _____ GUN #: 6340415
 PROOF: REM.-E INSP.: 9 TEST: 49 CODE: PT = 4/30
 HEADING: O.K. GRA./CAL.: 3008 PM
 BREECH OPENING: — CHECKED BY: C. PROBERT
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED - BROKEN COMPONENTS.

TRIGGER CONNECTOR CLEARANCE 1.068 (M/D = 1.079) TRIGGER

CLEARANCE 1.092 (M/D = 1.085) ENGAGEMENT .020 OR

TRIGGER PULL O.K. SLIGHT CORNER BREAKDOWN ON

SEAR & TRIGGER CONNECTOR CORNERS.

COMPLAINT: FIRES WHEN SAFE IS RELEASED.

INCIDENT: FOLLOWS DOWN

COMMENTS: CUSTOMER'S MALFUNCTION NOT CONFIRMED. IT IS
POSSIBLE WITH COMPONENTS SUCH AS THIS BUILT FOR THE
TRIGGER CONNECTOR TO WORK UP ON THE TRIGGER (CLEAR-
ANCE .017 OVER MAY). ALSO TRIGGER MAY HAVE FAILED TO
RETRACT DUE TO BIND IN THE TRIGGER GUARD CAUSED BY
OUT OF POSITION SCREW HOLES IN THE STOCK.