

RECEIVING AND ESTIMATING REPORT 1-

INITIAL LCS		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 09/17/90	DATE OPENED 09/27/90	DATE CODE DQ 9-78	SERIAL NUMBER A6181785	MODEL AND GRADE 788 22-250		ORDER 90-245	
ACCESSORIES L/CLIP		W/STUDS		L/ REAR SIGHT			

FROM: G & M GUNS RT 1 BOX 312A MOIRA NY 12957		SHIP TO: G & M GUNS RT 1 BOX 312A MOIRA NY 12957	
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED 10-3-90
WRITE ☐		VIA UPS	

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:	☐ NEW	☐ SLIGHTLY WORN	☐ VERY WORN	☒ MISUSED	☐ MARRED
CUSTOMER'S REQUEST	Gun goes off when taking safe off.				

MAIN FAULT	Tugger assembly has been removed from action after leaving factory. It appears that improper re-installation of assembly has resulted in damage to rear spring. It appears other alterations may have been made to assembly after leaving factory.
------------	--

PARTS	Send repair quotation as requested. Request of good-will quote & normal charge.				
REPAIRMAN RBS	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV.

OFFICE COPY