

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: GOOD R #: 005424
OUTSIDE WORK: TRIGGER STOP SCREW SEAL DATE: 2-25-72
FROM: DONALD GAGNON
FIRED AMMO TYPE: _____ CHICAGO, ILLINOIS
& CONDITION: _____ GUN #: 6362419
PROOF: R.E.P.-A INSP.: 58 TEST: 13 CODE: DT-9/70
HEADING: _____ GA./CAL.: 300 G SPR.
BREECH OPENING: _____ CHECKED BY: C. PROSSER
RECOIL SHOULDERS: _____ APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED COMPONENTS. HORIZONTAL ENGAGEMENT
.030 MIN. = .020 CONNECTOR CLEARANCE ON TRIGGER =
1.072 M/D = ^{1.079} 1.076 TRIGGER CLEARANCE ON CONNECTOR =
1.089 M/D = ^{1.083} 1.080. TRIGGER STOP SCREW SEAL BROKEN.
TRIGGER BIND DETECTABLE, LUBRICANT TOO HEAVY.

COMPLAINT: FIRES WHEN SAFETY IS RELEASED.

INCIDENT: TRIGGER FAILS TO RETRACT.

COMMENTS: THE FIT OF THE TRIGGER TO THE HOUSING, TOO
HEAVY LUBRICANT & EXCESS CLEARANCE BETWEEN
CONNECTOR AND TRIGGER (.010) COULD LEAD TO THE
CUSTOMER'S MALFUNCTION.