

12-20-88

Sir,

This rifle was returned to us by a customer. His explanation of its malfunction is as follows. Trigger pull was "mushy." Firing was delayed when trigger was pulled. At times the trigger could not be pulled with the safety off. This occurred several times. On one occasion, however, the gun fired when it was moved with no trigger pull. The gun also fired when the safety was cycled from off to on.

Our customer was very dissatisfied and more than a little alarmed. Please evaluate closely this rifle.

Bob Hill
Gouldin's Sports Center