

Mr. Sienkiewicz -

12-10-18

This Remington 30.6
(model 700) has fired when
the safety was released.
The gun was loaded, the
trigger was not bumped, squeezed,
or pulled... (nor was the gun)

As a result, our carpet
& floor now has a hole
in it. I figure \$50.00
would compensate for damages
& repairs.

I do hope the gun can
be fixed.

Thank you.
Deb Geier

phone #
208) 875 0304

Box 228
Pottlatch
Idaho
83855

2/27/78

ER GEIER

28 POTT LATCH IDAHO

6771922

04-7-74

... 3006

D BY: M-HARDY

ED: 1/12/79

ED: 1/12/79

ED: 1-12-79

ED: 1-12-79

RUSTY REC.

LEASED

200A

malfunction

C.B. 1-12-79