

P.I. NO GUN EXAMINATION REPORT NUMBER: 50 MODEL: 700 BOL
 GENERAL CONDITION: NEW- R #: 29532
 OUTSIDE WORK: SCOPE MOUNTED DATE: 12-8-82
 FIRED AMMO TYPE: UNKNOWN FROM: GELCHOFF, Inc.,
9625 Redwood Hwy.,
Belcham, AL 39106
 & CONDITION: _____ GUN #: B6330831
 PROOF: R.E.P. INSP.: 115 TEST: 118 CODE: 5-01
 HEADING: O.K. GA./CAL.: .30-06 Spec.
 BREECH OPENING: O.K. CHECKED BY: ABW
 RECOIL SHOULDERS: O.K. APPROVED: Jgt 1/11/83
 CHAMBER: O.K. APPROVED: PS 1/11/83
 TEST: _____ APPROVED: P.V. 1/11/83
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NEW

COMPLAINT: "... WHEN YOU PULL THE Bolt UP TO UNLOAD THE GUN,
THE SHELLS FIRE."

INCIDENT: _____

COMMENTS: Gun fails trick test, fire control appears to
full of crud impeding proper function of trigger
& other fire control parts. Front adjusting screws
have sealant removed.
Trigger pull 5 1/2 #
Seal lift .0105 - mill .0055
Replace fire control. - No change Jgt