

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: GOOD R #: 19457
OUTSIDE WORK: SCOPE MOUNTED. DATE: 10-4-71
FROM: GEN. SPT. SUPPLY CO.
FIRED AMMO TYPE: - SYRACUSE, N.Y.
& CONDITION: _____ GUN #: 6279663
PROOF: R.E.P.-E ^{ASSEMBLER 79} INSP.: 74 TEST: 87 CODE: ES = 10/69
HEADING: O.K. GR./CAL.: 3006
BREECH OPENING: - CHECKED BY: G. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO DAMAGED OR BROKEN COMPONENTS.

COMPLAINT: FIRES WHEN SAFE IS PUSHED OFF.

INCIDENT: _____

COMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE
DUPLICATED ANY WAY. IT WAS NOTED AND VERIFIED
BY K. CHADWICK THAT THE CUSTOMER HAD APPLIED
A LUBRICANT WHICH IS TOO HEAVY (THICK) TO THE
TRIGGER ASSEMBLY. THIS, IN COLD CLIMATES WOULD
CAUSE A MALFUNCTION SUCH AS THAT CLAIMED BY
THE CUSTOMER.