

To Whom it may Concern

Purchased This Rifle in
March 1994 From Bill
Hicks + Co.

HAS NEVER been Fired
Bolt make a squeaking
noise. Accidentally Dry Fired
Twice during operation
of Bolt, Please Repair
and Return to

Gibbs Gun Shop
RR 2 Box 234
Metter, GA 30439