

RECEIVED

APR 25 1983

RECEIVING AND ESTIMATING REPORT

DATE RECEIVED 3-30-83

ESTIMATED

4-25-83ORDER # 10815DATE OPENED 3-31-83

VIA

4/23MODEL AND GRADE 700 BDL-LH-270 Win

SERIAL NO.

B6368630W/Scope mounts

DATE CODE

KC5-82

FROM:

Gibbs Party Store
6469 South Morey Rd.
Mc Bain, Michigan
49657

REPAIR CHARGE 043980-55

INS.

UPS

PARCEL POST

TOTAL

\$

GUN CONDITION: (NEW) (SLIGHTLY WORN) (VERY WORN) (MISUSED) (QUOTE)

CUSTOMER'S COMPLAINT

Bolt lock softly installed

MAIN FAULT

Gun has new style Trigger Assem. Customer
want Bolt lock softly installed.
Could find no fault with Gun.

DEMERIT
CODE

PARTS

32895-Trigger Assem.
L.H

Fit old style Trigger
Assem. in Exchange

Polished Chamber
Closed Action

Work done

FOR COMPUTER REFER. ONLY

PROOF

(CLEAN) (TEST) (TARGET)