

4-5-61

Cost Complaint

IN EXAMINATION REPORT NUMBER: _____ MODEL: 700

DATE: 12-7-72

FROM: GRAF & SONS INC.

LOCATION: NEW

R # : 025981

OUTSIDE FROM: NO

FIRED AMMO TYPE: -

MEXICO, MO.

& CONDITION: ASSEMBLER P

GUN # : 643949.3

PROOF: R.E.P.-L INSP.: 73 TEST: 53

CODE: KU=5/71

HEADING: O.K.

G&A./CAL.: 25-06

BREECH OPENING: -

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010 (MIN. 15.020)BURRS ON SIDE OF TRIGGER.

COMPLAINT: "GUN GOES OFF WHEN BOLT IS CLOSED."

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION NOT DUPLICATED,
HOWEVER THE TRIGGER BIND COMBINED WITH UNDER
MIN. ENGAGEMENT MAY HAVE CAUSED A FOLLOW
DOWN.