

*Customer Complaint*P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 660GENERAL CONDITION: NEW R #: 15018OUTSIDE WORK: NO DATE: 7-28-71FROM: R.J. GRAMAZIOFIRED AMMO TYPE: — YARMOUTH, MASS.& CONDITION: _____ GUN #: 6210588PROOF: R.E.P. ^{ASSEMBLER #14} INSP.: 96 TEST: 32 CODE: LS = 2/69HEADING: O.K. GA./CAL.: .308BREECH OPENING: — CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN ETC. COMPONENTS. TRIGGER CONNECTOR -
SEAR ENGAGEMENT = .005 (.020 MIN.). SLIGHT UPSET AT
LEFT REAR CORNER OF HOUSING CAUSED BY THE FIRING
PIN HEAD CATCHING ON IT.

COMPLAINT: "GUN WENT OFF JUST PUTTING A SHELL IN THE CHAMBER"INCIDENT: FOLLOWED DOWN

COMMENTS: THERE WAS NOT ENOUGH ENGAGEMENT BETWEEN
THE TRIGGER CONNECTOR AND SEAR. THIS BEING REDUCED
TO ALMOST ZERO BY A SLIGHT TRIGGER BIND, LED TO THE
CUSTOMER'S MALFUNCTION.