

ATTN: REPAIRS

PLEASE FIND ENCLOSED ONE REM MODEL 700 KIT GUN IN 270 CAL
WITH BLACK RAM LINE STOCK & SLING S/N B6867503.


SQUACK: WHEN THE SAFETY WAS DISENGAGED THE GUN FIRED
THIS HAPPEND AFTER SEVERAL UNEVENTFUL SHOTS. I HAVE
HAD THIS MODEL 700 FOR FOUR YEARS NOW AND HAVE NEVER
HAD THIS HAPPEN BEFORE.

NEVER-THE-LESS EVERY SINCE I HAVE OWNED THIS GUN
THE SAFETY HAS BEEN VERY ROUGH AND HARD TO DISENGAGED
THIS PROBLEM COULD HAVE CAUSED A SERIOUS INJURY. I
ASSURE YOU THIS MISFIRE WAS CAUSED BY THE FORCE NEEDED
TO DISENGAGE THE SAFETY.

THIS WAS NOT CAUSED BY THE OPERATOR HAVING HIS FINGER
ON THE TRIGGER AT THE SAME TIME AS DISENGAGING THE
SAFETY. THERE WERE THREE WITNESSES WATCHING THIS INCIDENT
AND ALL THREE AGREE THAT HIS FINGER WAS OFF THE TRIGGER.
IT WAS OFF BECAUSE THE FORCE NEEDED TO REMOVE THE
SAFETY REQUIRED A HEAVY THUMB.

INSPECT AND REPAIR AS NECESSARY.
IF ANY REPAIR CHARGES ARE TO BE BILLED TO ME PLEASE
CALL BEFORE PROCEEDING.

HOME 316-524-6705
WORK 316-529-9546


KORBY GRAMKE