

Curt Camp

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: Good R #: 023332
OUTSIDE WORK: No DATE: 11-13-72
FROM: GRANTS' FOR GUN
INC.
COSTA MESA, CAL.
FIRED AMMO TYPE: - GUN #: 6449597
& CONDITION: _____ CODE: WV = 8/71
PROOF: REP-N ^{ASSEMBLER 73} INSP.: 87 TEST: 53
HEADING: O.K. GK./CAL.: 3006
BREECH OPENING: _____ CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR - TRIGGER CONNECTOR ENGAGEMENT = 0.10
(MIN. IS .020) BURRS ON SIDES OF TRIGGER

COMPLAINT: GUN FIRES WHEN SAFETY IS TAKEN OFF.

INCIDENT: FOLLOW DOWN

COMMENTS: IT APPEARS THAT TRIGGER BIND MAY HAVE
PREVENTED FULL RETRACTION OF CONNECTOR UNDER
THE SEAR REDUCING THE UNDER MIN. ENGAGEMENT
TO ZERO.