

Remington - Ammo - 150 gr. Corelok
Model 700 BDL 270 Cal.
Serial # - B6558525

10/94

Fred,

The accident happened on Jan. 31 '94 approximately 5:00 p.m. Weather conditions were cloudy and about 55°F. Humidity was low and a very little breeze. The gun was sitting in the seat of the truck, pointed downward into the floorboard. I reached down and took the gun from the safety position to the fire position and it fired unexpectedly. The bullet went through the firewall, the entire transmission, and rested in the freeze plug of the engine. The truck is a 1993 Chevy extended cab w/ about 19,000 miles. I did not touch the trigger and I cannot explain why the gun fired. This has never happened before and I have owned the gun for 2 years. I also tried to re-enact the same scenario and the gun would not do it again. If you need anymore info, please give me a call.

wk. (512) 984-6624

As of Jan. 15 '94

Hm. 102 Bryson Bend

Liberty Hill, Tx. 76642

(512) 515-5133

Sincerely,

Matt Grimm

Matt Grimm