

RECEIVING AND ESTIMATING REPORT

ORDER
R 94-13872

INITIAL FPS	CUSTOMER ORDER NO.					
DATE RECEIVED 04/21/94	DATE OPENED 04/22/94	DATE CODE PQ 6-78	SERIAL NUMBER A6619537	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	BDL
ACCESSORIES W/STUDS			W/SWIVELS		SCOPE BASE	

FROM:	SHIP TO:
GUN EXCHANGE INC 5317 W 65TH ST LITTLE ROCK AR 72209	GUN EXCHANGE INC 5317 W 65TH ST LITTLE ROCK AR 72209

CUST NO: 000191 ILION

ACCOUNT NUMBER	ACCOUNT NUMBER NYC	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION			REPAIR CHARGE \$0.00		
☐ NEW ☐ LIGHTLY WORN ☒ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED			EXCISE TAX INSURANCE UPS PARCEL POST TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Unable to duplicate upon receipt. Inspection reveals no obvious fault, trigger assembly removed & clean & ready to go, & gunny substance was found built up on both sides. With new & good cleaning.

Trigger Pin #42.45
300 ft. 008
#26345 Trigger Assembly
Comments: Replace complete trigger assembly and clean action at 1/2 normal replacement cost, as part of good work.
Go ahead

REPAIRMAN TAL	PROOF	CLEAN ☒	TEST ☒	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

to A/S 5/19/94