

Remington.



R 89-06307
Make Repair at
no-charge

REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

March 2, 1989

The Gun Shop
Clarence A. Berke
310 North Cane
Eunice, LA 70535

Dear Mr. Berke:

Examination has been completed on the Remington Model 700 25/06 caliber barrel action (less stock assembly and trigger guard), serial number A6287510, that you returned with the alleged complaint that the rifle fired sometimes when the safety was moved forward.

The returned firearm, which was produced in April of 1976, has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to being shipped from our factory.

The general condition of the above appeared to be good. In going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal. The trigger was found bent when opening the container.

Examination of the rifle and trigger assembly could not duplicate the reported malfunction. Many attempts were made to cause the rifle to fire when releasing the safe, without success. The only way the rifle could be made to fire is with the safety off and the trigger pulled, as designed. Trigger pull was measured to be 3-1/2 pounds, and sear lift with the safety in the on safe position was well within specification at .010.