

M/100 Custom Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: GOOD R #: 014102
 OUTSIDE WORK: SCOPE MOUNTED DATE: 7-14-72
 FROM: GUSTAVE GUNDERSON
 FIRED AMMO TYPE: - CONRAD, MONTANA
 & CONDITION: _____ GUN #: 6226860
 PROOF: R.E.P. ASSEMBLER 79 INSP.: 73 TEST: 87 CODE: AS-3/69
 HEADING: - GA./CAL.: 22-250
 BREECH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR - SEAR ENGAGEMENT .010 (MIN. IS .020) TRIGGER
PULL 2 1/2 LBS. (3 LBS. IS MIN.) RE-ADJUSTED BY CUSTOMER.
SEAR BEARING OF CONNECTOR CROOKED. TRIGGER MEASURED-
.008 UNDER MIN. ON CONNECTOR CLEARANCE, .002 OVER MAX. ON
6 IF PIN HOLE TO TOP.

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF TRIGGER PULL
TOO HEAVY.

INCIDENT: FOLLOW DOWN

COMMENTS: LIGHT TRIGGER PULL RESULTS IN ERRATIC RETRACTION.
THE TRIGGER HOLDING THE CONNECTOR TOO HIGH AND
ALLOWING IT TO WORK UP .008 TO INTERFERE WITH THE
SEAR COULD MAKE RETRACTION IMPOSSIBLE, FOLLOW
DOWN WOULD RESULT.