

RECEIVING AND ESTIMATING REPORT

COMMENTS

To Product Service

ORDER
R 94-03696

INITIAL
F.P.S.

CUSTOMER ORDER NO.

W/SOFT CASE

X.P. F. Suppy

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/28/94

01/31/94

XV 12-79

A6848928

700 243 WIN

ADL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

SHIP TO:

H & H SPORTING GDS & SUPPLUS
1517 CITY CENTER RD
MCKINLEYVILLE CA 95521

H & H SPORTING GDS & SUPPLUS
1517 CITY CENTER RD
MCKINLEYVILLE CA 95521

CUST NO: 034446 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW

☐ LIGHTLY WORN

☒ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☒ MARRED

\$2000
+ tax
+ shipping

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

While the safety is in the on position it can be moved just a fraction. When this happens the bolt opens and fires the gun.

MAIN FAULT

Date of Mfg. 12/79. Trigger safety in all positions pulled to could not duplicate customer concern. Trigger has been on outside of the factory and rear engagement changed. E. trigger arm at a special price as a gesture of goodwill and to restore his confidence in the rifle. We do not recommend that the trigger engagement be changed from the factory setting.

PARTS

COMMENTS

Trigger pull 1 3/4 lbs as Rec'd

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

GALLERY TESTER

DATE

DATE

DATE

DATE

OFFICE COPY