

Cost Corp

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL.
GENERAL CONDITION: NEW R #: 26180
OUTSIDE WORK: SCOPE MOUNTED, REGULAR DATE: 12-21-71
SIGHTS REMOVED. FROM: H.H. SPTG. QDS. INC.
FIRED AMMO TYPE: R.P. AMARILLO, TEXAS.
& CONDITION: ONE PIERCED PRIMER GUN #: 6334559
PROOF: R.E.P.-B INSP.: 71 TEST: 49 CODE: CT- 4/70
HEADING: O.K. GA./CAL.: 25-06 B.
BREACH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: TEN ROUNDS OF 120 GR. - NO PIERCED APPROVED: _____
PRIMERS, APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
FIRING PIN POINT TOO FLAT. TRIGGER CONNECTOR
DAMAGED. SEAR-TRIGGER CONNECTOR ENGAGEMENT
.005

COMPLAINT: RIFLE WILL NOT COCK.

INCIDENT: FOLLOWS DOWN.

COMMENTS: THE .010 UNDER MIN. ENGAGEMENT COMBINED WITH
BACKLASH FROM PIERCING PRIMERS BROKE DOWN
THE CORNER OF THE TRIGGER CONNECTOR RESULTING
IN THE FOLLOW DOWN MALFUNCTION.