

RECEIVING AND ESTIMATING REPORT

R ORDER
74-13475

FROM:

AZ 85213

SHIP TO:

AZ
85213

CUST' NO: 096180 G.I.D.

GUN CONDITION

☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE	20.00
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4				
REC. ASSY.		B5		D2	E4	F4
WOOD			C1		E5	F5
METAL			C2			

MAIN FAULT

MAIN FAULT Could not explain Custom Concern in this Aug 1974 mfg.
Process. Manufacturer found fault stop. Since would not admit, from Jimmy-
Stacy substance. Trigger engagement has been v. set outside our factory.

PARTS.

PARTS		COMMENTS				
Action and trigger assembly new Trip Pin 6/12/66 Pin 105		Replace complete trigger assembly as malfunction at 1/2 normal replacement cost, as failure of 1-2 pins will <i>be</i> <i>advised</i>				
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN	
		✓	✓			
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE	

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94