

RECEIVING AND ESTIMATING REPORT

CUSTOMER ORDER NO.			COMMENTS STEKL			ORDER		
DATE RECEIVED 10/02/86	DATE OPENED 10/09/86	DATE CODE	SERIAL NUMBER 6788266	MODEL AND GRADE 700 30-06 BDL		R 86-19405		
ACCESSORIES W/STUDS			BOTTOM HALF SEE THRU MTS					

FROM:

GIOVANONI HDWE., INC.
303 SILVER ST.
HURLEY, WI.

SHIP TO:

54534

COUNT NUMBER	TAX ST		INSURANCE	UPS	PARCEL POST	TOTAL
PAIR CHARGE	TAX CITY					\$

CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ QUOTE

CUSTOMER'S COMPLAINT

"When I load up, push in the bolt & pull down the bolt handle, it goes off"

MAIN FAULT

Under side of receiver & trigger assembly is loaded with partially solidified oil - trigger is very sluggish even in 75° office - bolt stop is nearly inoperative from dried out

DEMERIT CODE

RTS

Clean up (de-grease) trigger assembly re-test.

Lock was broken in shipment!

FOR COMPUTER REF. ONLY

PROOF

(CLEAN) (TEST) (TARGET)

REPAIRMAN

OFFICE COPY

07/10/86 REV. 1.0