

3-3/ 443-452

P.I. 755 GUN EXAMINATION REPORT NUMBER: 57MODEL: 700 BSLGENERAL CONDITION: GoodR # : 08810OUTSIDE WORK: SCOPE SCREWS REMOVEDDATE: 3-9-79FROM: P. HARRISONFIRED AMMO TYPE: U N K1000 V1312 B000 VSELA ST.
PLASTIC 22-1220& CONDITION: —GUN # : A6305900PROCP: REPOV INSP.: U TEST: 111CODE: K1-5-76HEADING: OKGA./CAL.: 243BREACH OPENING: OKCHECKED BY: M. H. - 900RECOIL SHOULDERS: OKAPPROVED: Sgt 3/30/79CHAMBER: OKAPPROVED: PL 3/30/79TEST: —APPROVED: PL 3-30-79

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: PL 3-30-79SHELL DENTS IN WOODDOB 3-30-79BRICK METAL IN WOODCOMPLAINT: RIFLE DISCHARGED WHEN SHOT
POSSIBLE FORWARDINCIDENT: BLEW A HOLE IN BED OF PICK
UP TRUCKCOMMENTS: Unable to duplicate incident. Weight
A full screw & overtravel screw not sealed indicating
they have been activated outside of Remington.