

19

W.F. Barrett
 J.E. Waiser
 E.G. Larson
 J.H. Chisnall
 R.B. Sperling
 F.D. Cole

1810

14, 1979

forward, the gun discharged,
 and blew a hole in the bed of
 her pick-up truck.

She insists she touched nothing
 but the forearm of the rifle and
 the safety with her thumb.

Since this is an unusually
 accurate rifle and I don't want
 to get rid of it, I called R. B.
 Sherman at Bridgeport, Conn.,
 and he suggested I send it
 to you.

I'm honest, I have to tell you
 I have tried repeatedly to make
 the gun go off under similar
 circumstances and it would not.

However, I have got to the

el 700 BDL .243 Win.
 ch allegedly fired
 tion.

and trigger assembly
 ave described. All
 to be normal, in-
 r, it appears that
 ant screws have been
 ad by the sealant

any, Inc., cannot ac-
 is incident. We can
 to the off position,
 ar. When the safety
 fted off of the trig-
 ffort is required to
 inector to be moved
 lition, on moving the
 fire.

stances that could
 and, as a gesture of
 ong with your present
 ither assembly at no
 file is restored, or,

the rifle can be returned as received. We will await your deci-
 sion and reply.

Thank you for having afforded us this opportunity to examine your
 rifle and to be of service.

Sincerely,

J.A. Stakl, Supervisor
 Firearms Product Service

JAS:tpf