

P.I. # 7 GUN EXAMINATION REPORT NUMBER: 87
GENERAL CONDITION: R-900
OUTSIDE WORK: SCOPE SCREWS REMOVED
FIRE AMMO TYPE: U N 71000 V
& CONDITION: —
PROOF: 9 E 000 INSP.: U TEST: III
HEADING: J K
BREACH OPENING: J
RECOIL SHOULDERS: J
CHAMBER: J
TEST: —
COMPONENT CONDITION: (Damaged, Broken, Old Style)
SCREW DRIVER IS MISSING
NO METAL AT MOUTH

MODEL: 700 PSL
R #: 08810
DATE: 3-9-79
FROM: R. HARRIS
1312 R-900 10 E-000 S
R-45-000 10 E-000 S
GUN #: A6305900
CODE: K1-5-76
GA./CAL.: 243
CHECKED BY: V L - 000
APPROVED: Sgt 3/30/79
APPROVED: Sgt 3/30/79
APPROVED: R/HB 3-30-79
APPROVED: (initials) 3-30-79
APPROVED: WGB 3-30-79

COMPLAINT: RIFLE DISCHARGED WHEN SAFE
WAS FORWARDED
INCIDENT: BLEW THROUGH TO BACK OF HEAD
UP TRUCK
COMMENTS: Unable to duplicate incident. Weight
A full screw & optional screw not sealed indicating
this has been initiated outside of Remington.