

REMINGTON ARMS COMPANY, INC.

ILI BN, NEW YBRK 18387
REPORT OF STATES

Ed Harts Gun Supply Rt. 415 Bath, N. Y. 14810

September 16, 1981

Model 700 Rifle A6550694 Repair Order R-18993-700

Dear Sir:

We recently received your Model 700, 22-250 caliber rifle, covered by your correspondence of recent date.

We have examined the gun, and we do find the fire control has been altered outside the factory, as we found all the adjustment screws not sealed, as they are preset at the factory.

Therefore, we do feel this did cause a problem, as we found nothing owrong with the components themselvesx.

The repairs are being done at no charge and we do expect to effect return shipment within one weeks.

We trust our actions will meet with your approval.

Cordially,

F. D. Cole:cm

Arms Service Division