

*Remington.*



**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

RECEIVED

JAN 25 1989

January 10, 1989

J.A. STEKE

Sports South, Inc.  
P.O. Box 51367  
410 Kay Lane  
Shreveport, LA 71135

Gentlemen:

Examination has been completed on the Model 700 270 Win caliber Mountain Rifle, serial number C6245584, that you returned to us a short time ago because "gun fires when closing bolt"

The returned firearm, which was produced in May of 1988, has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to being shipped from our factory.

The general condition of the gun appeared to be like new. In going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not duplicate the reported malfunction. Many attempts were made to cause the firing pin to fall upon bolt closing; all to no avail. Factory seals were intact on the trigger adjusting screws, indicating that no adjustment had been made to the trigger outside our factory. Trigger pull measured 4 1/4 pounds, and sear lift with the safety in the "on-safe" position was well within specifications at .011". The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed.