

ATTENTION Rodger POTTER
Remington Service Division

My. Remington 700 has a defective
Trigger/Safety.

A few weeks EARLIER while unloading it
it discharged (in the house). This happened when
I moved the safety to fire position to operate
the Bolt. I've gotten the ~~problem~~
problem to repeat on several occasions
while the gun was unloaded.

This was done by cocking the gun
and rapping on the stock as if it were
riding in a bumpy truck.

Also I use this gun for Varmint
hunting and target shooting. A light trigger
pull is a must after needed repair could
you adjust trigger pull? About 2 lbs or so.

Thank you

SN 6607224
Rem 700
22-250

JON A. HAYNES
RR 3 Box 211
Clinton IN.
47842