

RECEIVING AND ESTIMATING REPORT

OWNER ORDER NO.		COMMENTS	
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER
1/20/90	12/27/90	BC 1-82	86358734
ACCESSORIES	W/STUDS	L/SIGHTS	MODEL AND GRADE
			700 222 BDL
			ORDER
			R 90-33774

SHIP TO:	SHIP TO:
HEDGPETH, BILLY JOE	HEDGPETH, BILLY JOE
ROUTE 2 BOX 45	ROUTE 2 BOX 45
DEKALB MS 39328	DEKALB MS 39328

QUOTE	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
63103			1-10-91	V408864434

UISA	41271-3826-2023-0264
ISS. 955P	Ph 601-743-5443
	Exp 12/91

CHOOSE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
2560					
IN CONDITION:					
☐ NEW	☒ SLIGHTLY WORN	☐ VERY WORN	☐ MISUSED	☐ MARRED	
Guns fired without Touching Triggers					

Trigger assembly is contaminated with sticky, granular residue - internal trigger parts are not moving freely. Residue can be sticky on trigger assembly side plates. Sticky residue on bottom of receiver also. Trigger has not been properly maintained. Trigger pull 4 3/4 pounds, over lift .014"

6345 Trigger assembly 05000 offer to clean present trigger assembly (if possible) (M) we can install a new trigger assembly at 1/2 normal cost, as a gesture of good will, if this will better restore confidence in the rifle.

10982- New Follow-up
33450- 7000 RB SSN 22/250
33711- 21700 Bolt SSN
2 Customer 2/11/91 Est
New barrel SSN in 22/250
6715- Magazine
33697- 71700 Man SRN
2 New weeks
2/11/91

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
WES					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

4025 REV 7/80